



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-----------------|--------------------------------|-----------------|----------|
| 3 | T0310046 | Bolt 10x46 | | 1.00 |
| 16 | T4001016 | Washer 10,7x16,6x2,5 | | 1.00 |
| 19 | T3110003 | Nut M10 | | 1.00 |
| 20 | T4001026 | Washer 10,5,x26x0,5 | | 4.00 |
| 21 | BT27712005 | Bushing Linking 10mm | | 2.00 |
| 22 | C230001 | Gasket 15x21x2 | | 8.00 |
| 23 | BT27714009 | Bearing | | 4.00 |
| 25 | T0118038 | Screw 8x38 | | 2.00 |
| 26 | BT32100R3009 | Bushing | | 1.00 |
| 27 | T2108002 | Nut 8mm DIN 982 | | 2.00 |
| 34 | BT32000CT-CSV-2 | Rocker Arm Set | | 1.00 |
| 36 | T0210080 | Screw reas suspension 10x80 | | 1.00 |
| 37 | BT27712014 | Bushing Linking 8mm | | 2.00 |
| 39 | BT35000033012 | Special Screw Allen m10x125 12 | | 1.00 |
| 40 | BT34000CT-CSV-1 | Connecting rod cpl. | | 2.00 |
| 41 | T21010003 | Nut M10 | | 1.00 |