




| Pos | Part Number   | Description                  | Additional Text | Quantity |
|-----|---------------|------------------------------|-----------------|----------|
| 1   | 7503000210091 | Ignition cover               |                 | 1.00     |
| 2   | 49030090000   | DOWEL 9,8 X 7 X 10           | FS-E            | 2.00     |
| 3   | 60039040020   | generator line bracket       |                 | 1.00     |
| 4   | 07700240251   | o-ring 24.00x2.50 Viton      |                 | 1.00     |
| 5   | 6003009400030 | threaded plug M24x1.5 PA 6.6 |                 | 1.00     |
| 6   | 75030040000   | IGNITI.COVER GASKET 07       |                 | 1.00     |
| 7   | 75039004200   | Stator                       |                 | 1.00     |
| 8   | 76036075050   | INSET                        |                 | 2.00     |

|    |             |                               |  |      |
|----|-------------|-------------------------------|--|------|
| 9  | 75039005300 | Rotor                         |  | 1.00 |
| 10 | 0025060166  | HH collar screw M6x16 TX30    |  | 2.00 |
| 11 | 76636075000 | STICKCOIL HOLDER              |  | 1.00 |
| 12 | 76039006000 | STICK COIL                    |  | 2.00 |
| 14 | 60439093000 | SPARK PLUG M12X1.25           |  | 1.00 |
| 15 | 0025060256  | HH collar screw M6x25 TX30    |  | 4.00 |
| 16 | 0025060306  | HH collar screw M6x30 TX30    |  | 2.00 |
| 17 | 75039034000 | PULSER COIL                   |  | 1.00 |
| 18 | 59009062016 | SPECIAL SCREW M6X16 WS=8 10.9 |  | 2.00 |
| 19 | 60439094000 | SPARK PLUG                    |  | 1.00 |
| 20 | 0025060256S | SK-BUNDSCHRAUBE M6X25 ISA30   |  | 1.00 |
| 21 | 0025060306S | HH collar screw M6x30 TX30    |  | 3.00 |