




| Pos | Part Number     | Description                    | Additional Text | Quantity |
|-----|-----------------|--------------------------------|-----------------|----------|
| 1   | S455000003S0100 | Monoshock case M51x1 h19 with  |                 | 1.00     |
| 2   | S012900000S0100 | Compression cpl.               |                 | 1.00     |
| 3   | 14460042        | HS cylinder-head screw M5x20 D |                 | 1.00     |
| 4   | 50180095        | HS cylinder-head screw R1/8 I8 |                 | 1.00     |
| 5   | 50180217        | O-ring 27x1,5 Viton70 green IS |                 | 1.00     |
| 6   | 36120151S1      | screw fill M5x6 cpl.           |                 | 1.00     |
| 7   | 52000312        | Sticker XACT LDS 80x29         |                 | 1.00     |
| 8   | S938100001S0000 | SPRING SUPPORT                 |                 | 1.00     |
| 9   | 91210130        | mainspring (62/65) 36-240 muff |                 | 0.00     |
| 9   | 91210131        | mainspring (62/65) 39-240 muff |                 | 0.00     |
| 9   | 91210132        | Main spring (62/65) 42-240,muf |                 | 0.00     |

|    |                 |                                |  |      |
|----|-----------------|--------------------------------|--|------|
| 9  | 91210133        | Main spring (62/65) 45-240,muf |  | 0.00 |
| 9  | 91210134        | Main spring (62/65) 48-240,muf |  | 0.00 |
| 9  | 91210135        | mainspring (62/65) 51-245 muff |  | 0.00 |
| 9  | 91210136        | Mainspring (62) 54-250.0 shock |  | 0.00 |
| 10 | S828800000S01BQ | Spring seat 26,5x76,5x22,3 cpl |  | 1.00 |
| 11 | S208600003000FB | O-ring 5,28x1,78 HNBR70 red    |  | 1.00 |
| 12 | 50181207        | Locking nut M12x1 h9 WAF19     |  | 1.00 |
| 13 | 50181344        | Rebound disc 12x34x3,5 h0      |  | 1.00 |
| 14 | S625000000S0000 | Piston 12x49,4x18 cpl          |  | 1.00 |
| 15 | 50181091        | Rebound disc 12x43x12,5 h8     |  | 1.00 |
| 16 | 50180603S7      | Dichtungsträger 50x28 cpl.     |  | 1.00 |
| 17 | 50180126        | Round-wire snap ring 53x1,75   |  | 1.00 |
| 18 | 50181349        | Cap 50,12x16 h6                |  | 1.00 |
| 19 | 50181100        | Rubber pad 18x58x46 black      |  | 1.00 |
| 20 | S421800010S0100 | Mounting fork with piston rod  |  | 1.00 |
| 21 | RP10044T        | Repair kit adjuster DCC 2023   |  | 0.00 |
| 22 | 46811205        | Bush M10x12/15/13x9,5          |  | 1.00 |
| 23 | S918100006S0000 | adjuster rebound red cpl.      |  | 1.00 |
| 24 | R15006          | REPAIR KIT BEARINGS 07         |  | 0.00 |
| 25 | 50180218        | O-ring 25x1,5 Viton70          |  | 1.00 |
| 98 | 50180751S1      | SHOCK ABSORBER FLUID 5 LT      |  | 0.00 |
| 99 | RP10043T        | shock absorber rebuild kit     |  | 0.00 |